



# Water Quality Summary for the Logan Albert Rivers Catchment



Graph 1  
Average Suspended Solids for some SEQ Rivers  
(SEQRWQMS, 2001).



Graph 2  
Sediment Loads by Catchment  
(SEQRWQMS, 2001).






Lack of Buffering Capacity on the Logan River




Current Algal Blooms on the Teviot Brook


# Sediment and Erosion issues at Narangba







## Conflicting statements regarding regulatory protection of the Town Water Supply.



# Good Quality Agricultural Land

